



Assembly instruction 1/6

TOOLS—WORKERS



Φ7*39mm

A=45

Φ15mm

B=45

Φ8*40mm

C=34

Φ15mm

D=45

M4*16mm

E=3

M6*30mm

F=6

Φ13*10mm




G=6

5#


H=1

12"

L=2




(1)





NO.	Size	Quantity
3A-01	168x478x16	1
3A-06	1164x168x16	1

(2)



NO.	Size	Quantity
3A-02	168x496x16	1
3A-03	168x496x16	1
3A-07	780x40x16	1
3A-11	368x40x16	1



Φ7*39mm

A=45

Φ15mm

B=45

Φ8*40mm

C=34

Φ15mm

D=45

M4*16mm

E=3

M6*30mm

F=6

Φ13*10mm

G=6


5#

H=1

12"



L=2

(3)



N0.	Size	Quantity
3A-05	1200x500x16	1

(4)




Φ7*39mm
A=45


Φ15mm
B=45


Φ8*40mm
C=34


Φ15mm
D=45



M4*16mm
E=3


M6*30mm
F=6


Φ13*10mm
G=6



5#
H=1


12"
L=2











TOOLS—WORKERS

(5)



NO.	Size	Quantity
3A-04	1200x500x16	1

(6)





Φ7*39mm
A=45



Φ15mm
B=45



Φ8*40mm
C=34



Φ15mm
D=45



M4*16mm
E=38



M6*30mm
F=6




Φ13*10mm
G=6



5#
H=1




12"
L=2












TOOLS—WORKERS

(7)



TOOLS—WORKERS



Ø7*39mm

A=45

Ø15mm

B=45

Ø8*40mm

C=34

Ø15mm

D=45

M4*16mm

E=3

M6*30mm

F=6

Ø13*10mm

G=6


5#

H=1

12"


L=2

(8)




N0.	Size	Quantity
3A-10	363x80x16	1
3A-12	380x100x16	2
3A-13	380x100x16	2
3A-14	722x100x16	1
3A-15	310x100x16	1
3A-16	732x373x5	1
3A-17	373x320x5	1

(9)



N0.	Size	Quantity
3A-18	776x124x45	1
3A-19	364x124x45	1

(1)





φ7*39mm
A=45



φ15mm
B=45



φ8*40mm
C=34



φ15mm
D=45



M4*16mm
E=38



M6*30mm
F=6




φ13*10mm
G=6



5#
H=1




12"
L=2









TOOLS—WORKERS

(11)

