


Assembly instruction 1/4



φ7*39mm

φ15mm

φ8*40mm

φ15mm

M4*16mm

M6*30mm

φ13*10mm

5#

10"

L=1

A=22

B=22

C=17

D=22

E=26




F=4

G=4


H=1

L=1

TOOLS—WORKERS




(1)






NO.	Size	Quantity
5-01	188x346x16	1
5-02	188x346x16	1
5-04	364x188x16	1
5-05	364x40x16	1

(2)



NO.	Size	Quantity
5-07	400x350x16	1



φ7×39mm

A=22

φ15mm

B=22

φ8×40mm

C=17

φ15mm

D=22

M4×16mm

E=26

M6×30mm

F=4

φ13×10mm

G=4

5#



H=1

10"


L=1

TOOLS—WORKERS


(3)



(4)



(5)



NO.	Size	Quantity
5-03	400x350x16	1

NO.	Size	Quantity
5-08	270x80x16	1
5-09	270x80x16	1
5-10	306x80x16	1
5-11	316x263x5	1


φ7×39mm
A=22


φ15mm
B=22


φ8×40mm
C=17


φ15mm
D=22



M4×16mm
E=26



M6×30mm
F=4


φ13×10mm
G=4



5#
H=1


10"
L=1











TOOLS—WORKERS

(6)





NO.	Size	Quantity
5-12	764x178x45	1



(7)



(8)







TOOLS—WORKERS

φ7*39mm
A=22

φ15mm
B=22

φ8*40mm
C=17

φ15mm
D=22

M4*16mm
E=26

M6*30mm
F=4

φ13*10mm
G=4

5#
H=1

10"
L=1

