






Assembly instruction 1/4



Ø7*39mm
A=37

Ø15mm
B=37

Ø8*40mm
C=37

Ø15mm
D=37




M4*16mm
E=60

32&48
F=8


48*20*12mm
G=2

26*15*759mm
H=1

TOOLS—WORKERS




(1)





NO.	Size	Quantity
1-10	764x578x16	1
1-07	764x60x16	2

(2)



NO.	Size	Quantity
1-03	1907x764x16	1
1-04	764x500x16	1
1-09	764x578x16	1

Assembly instruction 2/4



Ø7*39mm
A=37

Ø15mm
B=37

Ø8*40mm
C=37

Ø15mm
D=37



M4*16mm
E=60

32&48
F=8


48*20*12mm
G=2

26*15*759mm
H=1

TOOLS—WORKERS




(3)








NO.	Size	Quantity
1-01	2000x580x16	1

(4)



NO.	Size	Quantity
1-02	2000x580x16	1

Assembly instruction 3/4



Ø7*39mm
A=37

Ø15mm
B=37

Ø8*40mm
C=37

Ø15mm
D=37

M4*16mm
E=60


32&48
F=8

48*20*12mm
G=2

26*15*759mm
H=1


TOOLS—WORKERS

(5)





NO.	Size	Quantity
1-05	1939x390x16	1
1-08	1939x45x16	1

(6)



NO.	Size	Quantity
1-06	1939x390x16	1



Ø7*39mm
A=37

Ø15mm
B=37

Ø8*40mm
C=37

Ø15mm
D=37

M4*16mm
E=60

32&48
F=8

48*20*12mm
G=2

26*15*759mm
H=1

TOOLS—WORKERS

