

Assembly instruction 1/1



M6*30mm
A=8






M4*20mm
B=12




5#
C=1


TOOLS—WORKERS




(1)



(2)



(3)



(4)

