

Assembly instruction 1/1



M6*30mm
A=8





M4*20mm
B=1




5#
C=1

TOOLS—WORKERS







(1)



(2)



(3)



(4)

