

Assembly instruction 1/1



M6*16mm
A=16




M4*20mm
B=9




4#
C=1




TOOLS—WORKERS



(1)



(2)



(3)

