

TOOLS- WORKERS



$\phi 7 \times 39 \text{mm}$
A=38

$\phi 15 \text{mm}$
B=38




$\phi 8 \times 40 \text{mm}$
C=26


15mm
D=38

M4*16mm
E=6




300*32mm
F=3

12''
H=4



(1)

NO.	Size	Quantity
AL-0-6	800 x 330 x 16	1

(2)

NO	Size	Quantity
A1-02	618x328x16	1


φ7*39mm
A=3


φ15mm
B=3


φ8*40mm
C=2




φ15mm
D=3


M4*16mm
E=6



300*32mm
F=3


12"
H=1

TOOLS—WORKERS




(3)




NO.	Size	Quantity
A1-01	618x328x16	1
A1-02	618x328x16	1
A1-04	774x628x5	1

(4)



NO.	Size	Quantity
A1-03	800x350x16	1

(5)



NO.	Size	Quantity
A1-05	283x80x16	1
A1-07	300x113x16	1
A1-08	300x113x16	1
A1-09	706x113x16	1
A1-10	716x293x5	1


ø7*39mm
A=3


ø15mm
B=3


ø8*40mm
C=2




ø15mm
D=3


M4*16mm
E=6



300*32mm
F=3


12"
H=1

TOOLS—WORKERS




(6)



NO.	Size	Quantity
A1-11	798x208x16	1

(7)



(8)

