

Assembly instruction 1/4



φ7*39mm
A=2


φ15mm
B=2


φ8*40mm
C=12




φ15mm
D=2





M4*16mm
E=3


M4*16mm
F=1



10''
H=1

TOOLS—WORKERS






(1)



NO.	Size	Quantity
2-01	328x138x16	1
2-02	328x138x16	1
2-05	364x188x16	1

(2)



NO.	Size	Quantity
2-04	400x330x16	1



Ø7×39mm
A=2



Ø15mm
B=2




Ø8×40mm
C=12



Ø15mm
D=2



M4×16mm
E=3





M4×16mm
F=1




10"
H=1


TOOLS—WORKERS




(3)



(4)




(5)



NO.	Size	Quantity
2-03	400x350x16	1

NO.	Size	Quantity
2-06	300x80x16	1
2-07	300x80x16	1
2-08	306x80x16	1
2-10	316x293x5	1

Assembly instruction 3/4



Ø7*39mm
A=2

Ø15mm
B=2

Ø8*40mm
C=12


Ø15mm
D=2

M4*16mm
E=3


M4*16mm
F=1

10"
H=1

TOOLS—WORKERS




(6)




N0.	Size	Quantity
2-09	398x151x16	1

(7)



(8)





Ø7*39mm
A=2



Ø15mm
B=2



Ø8*40mm
C=12



Ø15mm
D=2



M4*16mm
E=3




M4*16mm
F=1



10"
H=1

TOOLS—WORKERS



(9)

